Approved For Release 2001/05/05: CIA-RD#82-00457R007300140607 CLASSIFICATION CENTRAL INTELLIGENCE AGENCY REPORT NO. 25X1A INFORMATION REPORT CD NO. COUNTRY DATE DISTR. 15 Feb. 1952 USSR (Leningrad Oblast) NO. OF PAGES SUBJECT Leningrad/Pulkovo Airfield NO. OF ENCLS. PLACE 25X1A **ACQUIRED** RCULATE SUPPLEMENT TO DATE OF 25X1X REPORT NO. INFO.

- 1. The airfield was south of LEMINGRAD, immediately west of the road to PULKOVO (30°20°E/59°46°N) and on the south bordered on the Pulkovo Hills. The airfield administration building was half way between the southern perimeter of LEMINGRAD and the Pulkovo Hills, a distance of about five miles.
- 2. The following installations were completed:
  - a. By the end of 1947:

The runway, 5,000 x200 feet, the dispersal area, 2,650 x 330 feet. Runway and dispersal area, which were interconnected by two concrete roads, had a 12 inch concrete layer. According to the construction plan, the runway was to be 10,000 feet long.

b. By September 1949:

The airfield administration building, about 165 feet square, a three-story, fortress-like structure with four square annexes; a concrete road around the administration building, interconnected by concrete roads with the dispersal area and the highway to LEMINJRAD; hangar No. 3 with attached repair shops (see Annex).

3. The following installations were still under construction in September 1949:

Hangar No. 1, about 265x135 feet, steel structure, framework completed, still without roof;
Hangar No. 2, according to the inscriptions observed on it, a former German hangar, about 330x165 feet.

4. OF station and signal communications:

	•	CLASSIF <b>ICATI</b>	ON SECRET/COM	TROL-			25X6
STATE	NAVY	NSRB	DISTRIB	TION			
ARMY #	X AIR	X 181		Document	No. 7		
,	Approved I	For Release	2001/03/05 : 0	Declass	ngod To: <b>2:0:0</b> 2457F	— TS S∕ R0073 <del>0</del>	

## Approved For Release 2001/03/05: CIA-RDP82-00457R007300140007-3

25X6 SECKET/CONTROL

CENTRAL INTELLIGENCE AGENCY

25X1A

in following work was ander way:

a. Laying of underground cables around the runway and the taxe-off area which was scheduled to be 10,000 feet long.

b. Construction of an electrical and a telephone line between the runway and the DF stations a, b, and c (see innex). DF stations a and c were completed and in operation, DF station b was still under construction. The telephone cable to this station had, however, been laid.

c. Construction of tele hone and power transmission lines from the airport to the town and to the radio station about two miles northeast of the airfield administration building.

### 5. Power supply:

Power was supplied by a high-tension line from the Canned Heat Plant on the LANINGRAD-HOUSEV road, east of the field. A transformer station was about 300 feet east of hanger No. 3, from where the power was fed into underground lines. The dispersal area was provided with electric lines, but the lighting facilities were not in operation in September 1949, searchlights being used instead. The OF stations a and c were also connected with underground electric cables, but they were still supplied by a high-tension line leading from PULIOVO to the Pulkovo Observatory.

- 6. There was day and night flying. In September 1949, scheduled air lines to Finland, Kaliningrad, MOLJOJ, KIEV and to KHARLOV were in operation.
- 7. The following twin-engine aircraft were almost exclusively observed:
  - a. Former US Douglas aircraft
  - b. Aircraft with nose wheel

military craft were not observed at the field.

#### 25X1A

#### Comment:

a. The report presents a good picture of the stage of the construction work at the Pulkovo Airfield , particularly of the power supply and the scheduled electric lines. Report is in agreement with previous information

25X1X

25X1X

- b. Also of importance are the following negative statements that:
- (1) no military aircraft were seen t the field.
- (2) to construction of underground hangars on the Pulkovo Hills was observed .

SECKET/COUTROL

2

# Approved For Release 2001/03/05 CIA-RDP82-00457R007300140007-3

SHOUTHOUT 25X1A

CENTRAL LINE OF CHICK

- (3) The boundary lighting system was not connected with the electric line and correlights were in operation.
- c. The data on the observed connected absent types are in agreement with previous information.

Attach ent: Sketch of Pulkovo Airfield.

25X6

3.